
ULD Damage Report

Date: 2025-05-01

Inspector: Zein

Company: HU

ULD Type: AKE

ULD Serial: AKE 81262 8L

Location: OTHER

Damage Type: Dent

Severity: Moderate

Cause: Bagroom/Ramp

Action:

Notes: There is a big dent on the unit and there is also a puncture. It was found at D3