

---

# ULD Damage Report

**Date:** 2025-04-11

**Inspector:** Zein

**Company:** CZ

**ULD Type:** AKE

**ULD Serial:** AKE 77258 CZ

**Location:** D10 AREA

**Damage Type:** Dent

**Severity:** Minor

**Cause:** Bagroom/Ramp

**Action:**

**Notes:** The dent is located where the unit is winged, it is shown on the bottom right of the photo.