## **ULD Damage Report**

Date: 2025-03-13 Inspector: Zein Company: PR ULD Type: AKE

**ULD Serial:** AKE 20153 PR **Location:** D16 GRAVEYARD **Damage Type:** Puncture

Severity: Major

Cause: Bagroom/Ramp

Action: Notes: