

---

# ULD Damage Report

**Date:** 2025-02-20

**Inspector:** Zein

**Company:** Other

**ULD Type:** AKE

**ULD Serial:** AKE 65816 JD

**Location:** OTHER

**Damage Type:** Other

**Severity:** Moderate

**Cause:** Bagroom/Ramp

**Action:**

**Notes:** Door is bent not allowing it to close properly