

---

# ULD Damage Report

**Date:** 2025-05-16

**Inspector:** Zein

**Company:** EK

**ULD Type:** QKE

**ULD Serial:** QKE 61781 EK

**Location:** MENZIES

**Damage Type:** Broken Castor

**Severity:** Moderate

**Cause:** Bagroom/Ramp

**Action:**

**Notes:** The curtain door also has a tear in it