## **ULD Damage Report**

**Date:** 2025-05-19 **Inspector:** Manveer **Company:** CZ

ULD Type: AKE

**ULD Serial:** AKE79398CZ **Location:** Julliet graveyard

Damage Type: Dent Severity: Piggyback

Cause: Found damaged on airside piggyaback pmc 41572cz

Action: Notes:

