

# ULD Damage Report

**Date:** 2025-05-19

**Inspector:** Manveer

**Company:** EK

**ULD Type:** AKE

**ULD Serial:** Akl21734ek

**Location:** D16 GRAVEYARD

**Damage Type:** Dent

**Severity:** Major

**Cause:** Found damaged d16

**Action:**

**Notes:**

