

# ULD Damage Report

**Date:** 2025-05-19

**Inspector:** Zein

**Company:** UL

**ULD Type:** AKE

**ULD Serial:** AKE 0932 UL

**Location:** D16 GRAVEYARD

**Damage Type:** Tear

**Severity:** Minor

**Cause:**

**Action:**

**Notes:** Bottom right of the unit is where the tear is on the curtain door





