

# ULD Damage Report

**Date:** 2025-05-19

**Inspector:** Manveer

**Company:** EK

**ULD Type:** AKE

**ULD Serial:** 44313

**Location:** WAREHOUSE

**Damage Type:** Dent

**Severity:** Minor

**Cause:**

**Action:**

**Notes:**

