## **ULD Damage Report**

**Date:** 2025-05-19 **Inspector:** Manveer

Company: EK ULD Type: AKE ULD Serial: 40858

Location: WAREHOUSE Damage Type: Dent

**Severity:** Low

Cause: Returned Damaged by CT check date from group

Action: Notes:

