

# ULD Damage Report

**Date:** 2025-01-28

**Inspector:** Zein

**Company:** MU

**ULD Type:** AKE

**ULD Serial:** AKE 43117 MU

**Location:** D16 GRAVEYARD

**Damage Type:** Puncture

**Severity:** Minor

**Cause:** Bagroom/Ramp

**Action:**

**Notes:**

