

# ULD Damage Report

**Date:** 2025-02-20

**Inspector:** Zein

**Company:** EK

**ULD Type:** AKE

**ULD Serial:** AKE 41616 EK

**Location:** D16 GRAVEYARD

**Damage Type:** Puncture

**Severity:** Moderate

**Cause:** Bagroom/Ramp

**Action:**

**Notes:**

